



Product Change Notice (M.2 2242 A120-M Label Re-position)

Dear Valued Customers,

Apacer hereby announces the Product Change Notice of M.2 2242 A120-M series products, as re-position the label from non-controller side to controller side. Please refer to the below PCN tables for the detail.

PCN Number:	<i>E161125-01</i>	Released Date	<i>1125/2016</i>
Affected Product Model	<i>M.2 2242 A120-M</i>		
Subject :			
<i>M.2 2242 A120-M label re-position</i>			
Description of Change:			
<i>The current label position has caused thin client production issues due to it faces toward the motherboard after the installation. It is required to have the label position face up after installation.</i>			
Recommended Actions:			
<i>To meet customer's request. Apacer re-position the label to the controller side</i>			
Description of Product Part Number Change:			
<i>Photo to show the label re-position.</i>			
No Controller Side		Controller side	
Schedule:			
<i>Start from customer PO Date: 12/1/2016</i>			

If you have any questions and concerns with the content of this notice, please contact with your Apacer representatives.

Thank you for your continued support of Apacer products.

Embedded Application Product Division

Apacer Technology Inc.