

Product Change Notice

Update Firmware Version for UH110-UFD2 BiCS5 Products

Release date: Mar. 7, 2025

Dear Valued Customers,

Thank you for your business and continued support for Apacer products. This PCN is being issued to inform you of a firmware update for UH110-UFD2 BiCS5 products. Details of the change are provided in the table below. Apacer will provide all necessary support to ensure a seamless transition. If you have any questions or concerns regarding the content of this notification, please get in touch with Apacer sales representatives.

PCN Number	E250307-1	Release Date	Mar. 7, 2025
Action Levels	<input type="checkbox"/> Critical: Immediate change required <input type="checkbox"/> Warning: Change as soon as possible <input checked="" type="checkbox"/> Recommended: Optional, but suggested <input type="checkbox"/> Informational: No immediate action required		
Affected Product Model	UH110-UFD2 BiCS5		
Subject of Change			
To support secure firmware and to align firmware version with all other 3D TLC USB product lines, firmware version is updated from UFPA4ACA to UFPA4AJA for UH110-UFD2.			
Description of Change			
Apacer has updated the firmware version from UFPA4ACA to UFPA4AJA, respectively, with the following changes: 1. Add Secure Firmware. 2. Optimized error handling flow when host accesses non-existent LBA. 3. Fine-tune read-retry table 4. Support for 1024Gb.			
Recommended Action			
Apacer will continue to supply UH110-UFD2 BiCS5 with the old firmware, but we recommend qualifying with the latest version for improved compatibility and support.			

Affected Part Numbers

Capacity	Existing Part Numbers	New Part Numbers
	Standard Temperature	Standard Temperature
16GB	AN6.118GSL.00121	AN6.118GSL.00135

Schedule

Sample available date: Ready

Product Center

Apacer Technology Inc.