KING DESIGN®
Reliability & Communication Testing Instruments
KING DESIGN INDUSTRIAL CO., LTD.
VIBRATION TEST LABORATORY
4F,NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

REPORT NO：VT-200102-2

COMPANY ：Apacer Technology Inc.
ADDRESS ：1F., No.32, Zhongcheng Rd., Tucheng Dist.,
New Taipei City 236, Taiwan (R.O.C)
TEL ：886-2-2267-8000
FAX ：886-2-2267-2261
SPECIMEN ：SATA Flash Drive
DATE OF RECEIVED ：2019/11/18
DATE OF TESTED ：2019/12/18

TEST / INSPECTION ITEMS：Vibration / Shock Test

REMARKS：

- The laboratory is accredited by ISO/IEC 17025 General Requirements for the Competence of Calibration and Testing Laboratory.
- The results only apply to the device under test.
- This report is 26 pages, and no part of it may be abstracted or reproduced.

Test Engineer：Peter Peng	
Approval Signatory：David Lee 2020.1.6.	Laboratory Head：Hsin Tai Chang

KING DESIGN®
Reliability & Communication Testing Instruments
KING DESIGN INDUSTRIAL CO., LTD.
VIBRATION TEST LABORATORY
4F,NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

TESTING EQUIPMENT：

1.Vibration Tester	：KING DESIGN KD-9363EM-1000F2K-50N120, S/N：GUG02102091
2.Controller	：DACTRON LASER USB, S/N：12448370
3.Control Accelerometer	：WILCOXON RESEARCH WR-784A, S/N：23116
4.Shock Testing System	：KING DESIGN DP-1200-60, S/N：R2110086489
5.Controller	：DAS-105, S/N：263210255
6.Accelerometer	：B&K 4398, S/N：2209044
7.Shock Testing System	：KING DESIGN DP-1200-18, S/N：KDS02197998
8.Controller	：DAS-105, S/N：263210255
9.Accelerometer	：DYTRAN Model：3200B6 S/N：8594

TEST ENVIRONMENT：

Temperature	：25℃ (25±10℃)
Relative Humidity	：65% RH (50±25% RH)

SPECIMEN：

Model	：SX240-297
Quantity	：1 unit

KING DESIGN®
Reliability & Communication Testing Instruments
KING DESIGN INDUSTRIAL CO., LTD.
VIBRATION TEST LABORATORY
4F,NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

TEST SPECIFICATION(1)：

Comply with MIL-STD 810G 514.6 category 7

Random Vibration test (Non-Operating)

Frequency	：15 Hz to 2,000 Hz
Accelerate	：4.02 g rms
P.S.D.	：0.01 g^2/Hz (15Hz)
	0.01 g^2/Hz (105.94Hz)
	+6 dB/Oct (105.94Hz to 150Hz)
	0.02 g^2/Hz (150Hz)
	0.02 g^2/Hz (500Hz)
	-6 dB/Oct (500Hz to 2,000Hz)
	0.0013 g^2/Hz (2,000Hz)
Test Axis	：X, Y, Z axis
Test Time	：1 hr (Each axis)
Total Test Time	：3 hrs

TEST SPECIFICATION(2)：

Comply with MIL-STD 810G 514.6 category 24

Random Vibration test (Operating)

Frequency	：20 Hz to 2,000 Hz
Accelerate	：7.69 g rms
P.S.D.	：0.04 g^2/Hz (20Hz to 1,000Hz)
	：-6 dB/Oct (1,000Hz to 2,000Hz)
Test Axis	：X, Y, Z axis
Test Time	：1 hr (Each axis)
Total Test Time	：3 hrs

KING DESIGN®
Reliability & Communication Testing Instruments
KING DESIGN INDUSTRIAL CO., LTD.
VIBRATION TEST LABORATORY
4F,NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

TEST SPECIFICATION(3)：

Comply with MIL-STD-883K Method 2002.5

Wave Form ：Half sine wave (Non-Operating)
Acceleration ：1,500 g
Duration Time ：0.5 mS
No. of Shock ：Each axis 3 times
Shock Direction ：±X, ±Y, ±Z axis

TEST SPECIFICATION(4)：

Comply with MIL-STD-202G,Method 213B

Wave Form ：Half sine wave (Operating)
Acceleration ：50 g
Duration Time ：11 mS
No. of Shock ：Each axis 3 times
Shock Direction ：±X, ±Y, ±Z axis

TEST RESULT：

Describe	PASS	FAIL	Non-Judgment
Function judgment(1)	√	——	——
Appearance check(2)	√	——	——
(1)--Burn in function was normal after the test. (2)--No visible damages were found after the test.			

KING DESIGN®
Reliability & Communication Testing Instruments
KING DESIGN INDUSTRIAL CO., LTD.
VIBRATION TEST LABORATORY
4F,NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

Sample photo before the test
Front

Back


KING DESIGN INDUSTRIAL CO., LTD.
4F,NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
VIBRATION TEST LABORATORY
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

Vibration testing photos	
X axis (Operating)	X axis (Non-Operating)
	
Y axis (Operating)	Y axis (Non-Operating)
	
Z axis (Operating)	Z axis (Non-Operating)
	

KING DESIGN®
Reliability & Communication Testing Instruments
KING DESIGN INDUSTRIAL CO., LTD.
VIBRATION TEST LABORATORY
4F,NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

Shock testing photos (Non-operating)	
+X axis	-X axis
	
+Y axis	-Y axis
	
+Z axis	-Z axis
	

KING DESIGN INDUSTRIAL CO., LTD.
4F,NO. 3, Lane 270, Pei Shen Road Sec. 3,
Shen Keng Dist., New Taipei City, 222, Taiwan, R.O.C
TEL: 886-2-2662-5100 FAX: 886-2-2662-3094
VIBRATION TEST LABORATORY
http: //www.kdi.tw
http://www.vibration.com.tw
E-mail:service@kdi.tw

TESTING / INSPECTION REPORT

Shock testing photos (Operating)	
+X axis	-X axis
	
+Y axis	-Y axis
	
+Z axis	-Z axis
	

X axis



Level: 100.00 %
Drive Pk: 0.445V
Est. Disp. : 1.827 mm Pk-Pk
Velocity Pk: 137.6 mm/s
Control RMS: 4.073 g
Target RMS: 4.020 g
Remaining: 00:00:00
Total Elapsed: 01:01:01
Full Level Elapsed: 01:00:00

Y axis



Level: 100.00 %
Velocity Pk: 134.5 mm/s
Remaining: 00:00:00

Drive Pk: 0.424V
Control RMS: 4.077 g
Total Elapsed: 01:01:01

Est. Disp. : 1.753 mm Pk-Pk
Target RMS: 4.020 g
Full Level Elapsed: 01:00:00

Z axis



Level: 100.00 %
Velocity Pk: 136.1 mm/s
Remaining: 00:00:00

Drive Pk: 0.437V
Control RMS: 4.071 g
Total Elapsed: 01:01:01

Est. Disp. : 1.796 mm Pk-Pk
Target RMS: 4.020 g
Full Level Elapsed: 01:00:00

X axis



Level: 100.00 %
Drive Pk: 0.800V
Est. Disp. : 2.226 mm Pk-Pk
Velocity Pk: 222.8 mm/s
Control RMS: 7.773 g
Target RMS: 7.690 g
Remaining: 00:00:00
Total Elapsed: 01:01:02
Full Level Elapsed: 01:00:00

Y axis



Level: 100.00 %
Drive Pk: 0.800V
Est. Disp. : 2.250 mm Pk-Pk
Velocity Pk: 223.0 mm/s
Control RMS: 7.780 g
Target RMS: 7.690 g
Remaining: 00:00:00
Total Elapsed: 01:01:02
Full Level Elapsed: 01:00:00

Z axis



Level: 100.00 %
Drive Pk: 0.821V
Est. Disp. : 2.189 mm Pk-Pk
Velocity Pk: 219.8 mm/s
Control RMS: 7.783 g
Target RMS: 7.690 g
Remaining: 00:00:00
Total Elapsed: 01:01:03
Full Level Elapsed: 01:00:00

+X axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	1589.74	0.48	4.53	10000.00	1589.74	-438.74



-X axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	1575.26	0.48	4.43	10000.00	1575.26	-491.98



+Y axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	1547.12	0.48	4.37	10000.00	1547.12	-538.58



-Y axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	1578.17	0.48	4.41	6000.00	1578.17	-545.94



+Z axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	1592.19	0.47	4.42	6000.00	1592.19	-549.22



-Z axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	1577.94	0.55	4.68	10000.00	1577.94	-793.70



+X axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	51.73	11.78	3.73	500.00	51.73	-6.57



-X axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	51.96	11.78	3.75	500.00	51.96	-6.05



+Y axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	52.18	11.74	3.75	500.00	52.18	-5.67



-Y axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	52.13	11.74	3.75	500.00	52.13	-5.56



+Z axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	52.18	11.75	3.75	500.00	52.18	-5.61



-Z axis

Signal		Acceleration (gn)	Duration (ms)	Velocity (In/s)	Filter (Hz)	Max Acc (gn)	Min Acc (gn)
Input1(t)	■	52.09	11.75	3.75	500.00	52.09	-5.45



-END-