

Product Change Notification

The Location Change of Engraved Logo on Housing for USZ20-UFD5/US120-UFD5/ UM120-UFD5/UV110-UFD5/UH110-UFD5 Products

Release date: Jan. 2, 2025

Dear Valued Customers,

Thank you for your business and continued support for Apacer products. We are issuing this PCN to inform you of the location change of engraved CE/FCC logo on USZ20-UFD5/US120-UFD5/UM120-UFD5/UV110-UFD5/UH110-UFD5 products. The details of the change are outlined in the table below. If you have any questions or concerns about this notification, please contact your Apacer sales representative.

PCN Number		
E250102-1		
Subject of Change		
The location of the engraved CE/FCC logo on USZ20-UFD5/US120-UFD5/UM120-UFD5/UV110-UFD5/UH110-UFD5 products will be updated to accommodate a new engraving method applied to the housing.		
PCN Type		
<input type="checkbox"/> Design change	<input type="checkbox"/> BOM change	<input checked="" type="checkbox"/> Package/Mechanical change
<input type="checkbox"/> Manufacturing change	<input type="checkbox"/> Production process	<input type="checkbox"/> Technical document
<input type="checkbox"/> Others (Part number)		
Products Affected		
USZ20-UFD5/US120-UFD5/UM120-UFD5/UV110-UFD5/UH110-UFD5		
Description of Change		
A new mold, "M5," has been adopted to replace the previous mold, "M4," for producing housings. The location of the engraved CE/FCC logo created using the "M5" mold differs from that of the "M4" mold, as shown in the photos below. The material and surface treatment remain unchanged, with only the engraved CE/FCC logo updated to accommodate the new engraving method applied to the housing.		

Old	New
<p data-bbox="108 302 464 331">A housing made by M4 Mode:</p> 	<p data-bbox="812 302 1168 331">A housing made by M5 Mode:</p> 

Effective Date of Implementation

Running change after the old housing inventory is used up.

Product Center

Apacer Technology Inc.