

TESTING / INSPECTION REPORT




REPORT NO : TT-100408-2

COMPANY : Apacer Technology Inc.
ADDRESS : 9F, 100, Sec.1, Hsin Tai Wu Rd.,
Hsichih Taipei Hsien 221, Taiwan, R.O.C.
TEL : 886-2-2696-1666
FAX : 886-2-2696-1668
SPECIMEN : ADMIII 44P/180D LP without dot board
DATE OF RECEIVED : 2010/03/05
DATE OF TESTED : 2010/03/29

TEST / INSPECTION ITEMS : Temperature Test

REMARKS :

- The laboratory is accredited by ISO/IEC 17025 General Requirements for the Competence of Calibration and Testing Laboratory.
- The results only apply to the device under test.
- This report is 7 pages, and no part of it may be abstracted or reproduced.

Test Engineer :	
	
Approval Signatory :	Laboratory Head :
 2010.4.19	

TESTING / INSPECTION REPORT

TESTING EQUIPMENT :

Chamber : KING SON THS-D4C-150, S/N:2682

TEST ENVIRONMENT :

Temperature : 23.5°C (25±10°C)
Relative Humidity : 66% RH (60±20% RH)

SPECIMEN :

Model : ADMIII 44P/180D LP without dot board
Quantity : 2 pieces

TEST SPECIFICATION :

(1) Temperature Test (Operation Test)

Step	Temperature (°C)	Duration
1	0	96 hrs
2	70	96 hrs

Test Cycle : 1 cycle
Total Test Time : 192 hrs

(2) Temperature Test (Non-Operation)

Step	Temperature (°C)	Duration
1	100	96 hrs
2	-40	96 hrs





Test Cycle : 1 cycle
Total Test Time : 192 hrs

TESTING / INSPECTION REPORT


TEST RESULT :


Describe	PASS	FAIL	Non-Judgment
Function judgment	√	---	---
Appearance check	√	---	---

TESTING / INSPECTION REPORT


Testing photos	
Sample 1-1	Sample 1-2
	
Sample 2-1	Sample 2-2
	

TESTING / INSPECTION REPORT





Temperature Test (Non-Operation)



-END-